## Specifications

Item	Specifications
Sensor frequency	60KHz
Measuring range	50mm ~ 350mm
Accuracy	10mm
Signal Output Method	UART
Operating temperature	-10°C ~ +50 °C
Relative humidity	≤ 95%
Power supply voltage	3.3~5V