


Dimensions



Specifications

Item	Specifications
Sensor frequency	40KHz
Measuring range	20mm ~ 2500mm
Accuracy	10mm
Signal output method	UART
Operating temperature	+5°C ~ +50 °C
Relative humidity	≤ 85%
Power supply voltage	DC 5V
Current	< 10mA